Leaking Serpentine Belt Tensioner

(Source: Mazda TSB 01-019/19)

Affected Models:

- 2016-19 CX-3, 2016-19 CX-9, 2014-19 Mazda3, 2013-19 Mazda3 (Mexico)
- 2012-19 CX-5, 2016-19 MX5, 2014-19 Mazda6, 2017-20 Mazda6 (Mexico)

The models listed above may exhibit an oil leak from the drive belt hydraulic tensioner and a rattle from the engine compartment. These symptoms result from a leaking seal on the hydraulic damper, especially under high loads and high ambient temperatures.

Replacing the tensioner assembly and drive belt will solve the issue. An old-style tensioner can be identified by the serial number **F569897.10**. The new tensioner can be identified by the serial number **F569897.13**. Since the OEM part number (PET2-15-980) remains the same, it is imperative to use the serial number to identify an old-style tensioner.

The Continental number for the damper is 49858 and the drive belt is 4060382. If the stretch-fit water pump belt is contaminated with oil, it must be replaced. There are two choices for the water pump belt, so please refer to the Continental parts catalog for the correct part number.



DISCLAIMER: While every effort has been made to substantiate the information contained in this Component Alert, Continental will not warrant its accuracy or completeness. Continental assumes no responsibility for any loss, injury, damage, or expense directly or indirectly due to errors or omissions or arising out of or relating to use or reliance on the information contained herein. The information contained herein is not, intended to replace manufacturer's operating or safety instructions and is subject to change without notice. To obtain the most current data, please refer to the latest recommendations from the appropriate manufacturer. Manufacturer's and Continental's liability is limited solely to replace the defective materials or workmanship.
IN NO EVENT SHALL MANUFACTURER OR Continental BE LIABLE FOR ANY SPECIAL, INDIRECT, INCIDENTAL OR CONSEQUENTIAL DAMAGES.